

INSTALLATION MANUAL

CONDENSATION MANAGEMENT KIT FOR QUEST 4000 (629096996)

INSTALLATION:

1. Remove the existing legs from the unit.
2. Attach the right weldment to the unit with the supplied screw and washer using a 9/16" crescent wrench.
3. Attach left weldment to unit with supplied screw and washer.
4. Bolt the provided 2-1/2" legs onto the left and right weldment.
5. Slide the drip tray into the slot with the hand relief facing forward.
6. Attach optional drain to tray by drilling out the relief in the tray with a 7/8" diameter drill.

Table 1. Kit Contents

Item Number	Part Number	Description	Quantity
1	620047625	Leg, Right Weldment	1
2	620047629	Leg, Left Weldment	1
3	46593003	Bolt, MA 3/8-16 HX	4
4	20223008	Washer	4
5	620047626	Drip Tray	1
6	7229602	Fitting, Conn Drain	1
7	37958001	Leg – Level 2 1/2" Adjustable	4




Figure 1. Kit Assembly